



Corby Energy Services, Inc.

About Us

- WBENC Certified since 2012
- Detroit-based business since 2015
- Approx. 450 Employees (mostly Michigan-based)
 - All field employees are QEW-trained (Qualified Electrical Worker)
 - Most field employees are OQ Qualified (Operator Qualification)



METRO ENGINEERING SOLUTIONS



METRO CONSULTING ASSOCIATES

Overhead
Lines, LLC



Corby Energy Services, Inc.



PATRIOT MANUFACTURING



Michigan Locations



2021 S. Schaefer Hwy., Detroit, MI 48217



6001 Schooner St., Belleville, MI 48111



45345 Five Mile Rd., Plymouth, MI 48170



7929 E. M-36, Whitmore Lake, MI 48169

Current Customers

Multi-year contracts with Michigan utilities:

DTE Energy (Electric/Gas/Streetlighting/Major Enterprise Projects)

- Blanket contracts which include joint service and commercial feeder work with numerous utilities including CMS Energy, AT&T, Comcast, etc.

AT&T

- Copper and fiber underground and aerial placing, repair and maintenance

CMS Energy

- Distribution operations – new business and rehabilitation

MDOT

- Directional drilling, lighting, communications and traffic control/signaling services

Various cities and municipalities

- Water and sewer services
- Streetlighting
- Pipeline rehabilitation and inspection (bursting, lining, CIPP, chemical grouting, cctv, etc.)

Service Offerings

CES is an infrastructure solutions provider, specializing in:

Trenchless Utility Construction

- Horizontal Directional Drilling
- Cured-in-Place-Pipe (CIPP)
- Slip Lining
- Pipe Bursting

Traditional Excavation and Site Work

- Infrastructure Construction/Rehabilitation/Renewal

Design/Build

- Complete EPC capabilities with our affiliated firms (includes engineering, survey, permitting, procurement, warehousing, construction)



Slope Restoration



May 10, 2022







Pipeline Renewal Methods



Critical Steps to Trenchless Pipe Projects

- Define the problem in the piping system via various methods or procedures
- Select alternatives that are considered appropriate for the repair the pipes
(Cost + Quality = Value)
- Determine the method of procurement?



Trenchless Technologies

- Pipe bursting
- Cured-in-Place-Pipe
- Fold & Formed / UltraLiner
- Horizontal Directional Drilling
- Grouting / CCTV Inspection / Cleaning
- Engineering / Design Build
- Sliplining
- Large Diameter Pipe Rehabilitation
- Excavation / Open Cut



Pipelinebursting

Some Trenchless Project Owners

- City of Warren
- City Jacksonville
- City of Livonia
- City of Monroe
- City of Auburn Hills
- City of Grosse Pointe Woods
- City of Center Line
- Chesterfield Township
- City of Fraser
- City of Saint Clair Shores
- City of Traverse City
- City of Ann Arbor
- City of Ypsilanti
- City of Grosse Pointe Farms

- City of Detroit
- Watertown Township
- City of St. Petersburg
- City of Live Oak
- City of Houston
- City of Austin
- City Jacksonville
- City Fort Oglethorpe
- City of Dallas
- City of Seattle
- City of San Antonio
- City of Atlanta
- City of South Lyon
- City of Lansing
- City of Orlando

Departments of Transportations

- **Michigan**
- **Indiana**
- **Alabama**
- **Arkansas**
- **New York**
- **Florida**

Universities

- **Michigan State University**
- **University of Michigan**
- **University of Notre Dame**
- **University of Arlington**
- **Louisiana Tech**

Pipebursting: Today vs. Then

- Greater recent advancement providing wider application / project history
- More reliable today than five years ago
- More cost-effective
- Wider acceptance and more usage
- Better Equipment and Materials
- Increased knowledge of successful equipment, means, methods and materials
- Better understanding from the owner and engineering communities of benefits



Advantages to Trenchless Technologies


- 85% less carbon footprint than open-cut
- **Pipe Bursting “*Green Technology*”**
- Owner gets compliments instead of complaints from the public
- Cost savings average 30% less than open excavation
- Less public disruption than open-cut
- Utilizing existing conduit in easements
- Less risk to owner & contractor for safety issues.
- Normally change orders don't exist unless more work added
- Reduce project duration



Large Diameter Pipe Bursting Considerations


- Depth
- Existing pipe material
- Ground water
- Existing Soils
- Age of Construction
- Back fill materials
- Shoring and Bracing machine

Pipebursting Upsize Capabilities




Static Pipe Bursting Step 1

- Inspect existing sewer by CCTV
- Excavate machine and new pipe insertion pits
- Excavate service pits if required
- All pits to be properly shored and maintained dry




Static Pipe Bursting Step 2

- Prepare machine pit
- Set up Static pipe bursting machine in pit
- Push rod string through host pipe (existing sewer)
- From machine pit to new pipe insertion pit




Static Pipe Bursting Step 3

- The rod string emerges at new pipe insertion pit
- Attach pipe bursting head and new replacement pipe to
- The rod string
- In this case HDPE pipe already fused into a single
- Continuous length is shown and the set up is ready for
- The actual pull back replacement process



Static Pipe Bursting Step 4

- Static pipe bursting machine in machine pit is
- Set up for pull back operation
- The rod string pulls the bursting head towards the
- Machine pit
- The bursting head breaks the existing sewer and
- Pushes the broken pieces into the surrounding
- Ground, away from the center and creating a new
- Tunnel
- The bursting head advances towards the machine pit
- And installs the new HDPE pipe in-place





Pipe Bursting Case Study

University of Notre Dame

- Bursting 7,000 ft of 12" VCP existing VCP upsizing to 18" HDPE SDR 17.
- Depth 25' to 35'
- 1,200' pulls thru existing manholes
- 225-Ton Static Pipe Burst Machine

By-pass



Female Dorm



May 10, 2022

Support of Main Electric Conduit



Set-up of Pipe-Burst Machine



Pipe Fused Across Campus



May 10, 2022

Entry Pit



Supporting Pipe at Entry Pit



Supporting Pipe at Entry Pit




Entry Existing 12" VCP OD 22" Expander



Pushing Down on Pipe to Maintain Grade



Bursting Machine Inside 12'X12' Manhole Box




May 10, 2022

Pipe Exit



Entry pit



Burst Machine Removed

Burst-Head Removed



May 10, 2022

Manhole Set to Connect Two Pipe-Burst Installations



May 10, 2022

Removing Invert to Burst Through Existing Manhole



Pipe-Rammed Under Discovered Fiber-Optic Vault



May 10, 2022

Pipe Through Rammed Casing



Burst Entering Through Existing Manhole - 1,000' pull.



Ready to Begin Burst



May 10, 2022

Pipe Train



May 10, 2022

Entry Pit 25' Deep







Pipe Bursting Case Study

- Pipe Bursting existing 3 layer 30" brick sewer upsizing to 36" HDPE SDR 17.
- Depth 20' to 25' in deep
- 800' pulls thru existing manholes
- 225-Ton Static Pipe Burst Machine



Burst Head Attached



Pipe Train



May 10, 2022







Burst Machine Pit





Burst Head Entering Existing 30" RCP



Entering Existing Pipe



Bursting Through Manhole in Road



Entering Exit Pit



Burst complete



Fort Oglethorpe, Georgia

Design Build

- **Pipe Burst and CIPP 9,000 LF of 24" RCP Sanitary Sewer**
- **CCTV/Cleaning**
- **Static Burst System**



May 10, 2022

Pipe-Burst Equipment



Pipe-Burst Head



May 10, 2022

HDPE Pipe Entry Pit



May 10, 2022

HDPE Pipe Entry Pit



Pipe Bursting-Case Study

MDOT Project on I-94 East bound lanes, at Sprinkle Road Exit.

- There was a collapse in the center of the east bound lanes.
- Existing pipe was 16" RCP. Stayed with same size HDPE as end product.
- Burst was completed in one night never closing I-94.
- Using static burst system.
- 225 Ton Static Pull

Sink Hole in Fast Lane



Sink Hole



Burst Machine Set



Maintained Traffic Flow



Fused HDPE on Shoulder



Burst Head



Entry Pit



Bursting Through Existing Catch Basin



Pipe-Burst Head Reaching Machine





Pipe-Burst Case Study

Michigan Department of Transportation Project on M-13

- **Failing 30" Reinforced Concrete Pipe Burst 30" HDPE**
- **Bay City, Michigan**

Setting-Up



Inside Existing 30" RCP



Driving I-Beams



During Pipe-Burst Pull Back



Above Pipe



May 10, 2022


Pipe Train



May 10, 2022

Burst Head Enters Burst Pit





Pipe Bursting-Case Study

42" Culvert Metal Pipe

- **Wolverine, Michigan**
- **Existing 42" CMP 35' in depth**
- **TRS-225 Ton pipe bursting machine**

PRIVATE PROPERTY
AUTHORIZED PERSONNEL
ONLY
Wildwood Valley Property
Owners Association Club

21 12:24 PM



21 12:40 PM




21 12:34 PM


Outfall Pipe – Tar Lined CMP




















Burst Machine Set Back to Allow Pipe to Enter Pit







Case Study

48 in. CMP Pipe Burst

- Emergency 48 inch Collapse under Michigan Department of Transportation Highway M-106

Sink hole on upstream side



Pipe Collapse in shoulder



Upstream end







Down stream end of pipe





Pull head fused on













Notice gas pipeline marker for 12 high pressure steel





















Pipe installed exit side



Machine side pipe installed



Completed






sliplining

Sliplining

- 4" thru 120" diameters
- Continuous or segmental
- With flow or by-passed
- HDPE Pipe
- Bulk Head
- Grout annulus





Slip-Line Case Study

Tanner Creek 84" Culvert

- 520' Slip-line with 72" HDPE
- 60' under 1-94 mile marker 16

BERRIEN COUNTY DRAIN COMMISSION
Michigan Department of Transportation

Existing Outfall



May 10, 2022

Downstream End 84" CMP Bottom Rotted Out



Up-stream – Bend in Pipe



I-94 60' Above



Adding Sections of Pipe By-Pass Run Through Pipe



Adding 50' Section of Pipe



Aligning Pipe for Welding



Extrusion Welding Pipes Together



Pipe Installed - Grout Tubes



Bulk Head Complete and Grouted Rip-Rap Installed



Complete



May 10, 2022

140



Slip-Line Case Study

42''' Culvert

- 485' Slip-line
- 30' under US-127 and M-10

Michigan Department of Transportation









Sliplining Existing 42" Culvert



Pipe laid out























Slip-Line Case Study

66" Culvert

- 360' Slip-line
- 70' under I-196

Michigan Department of Transportation
































Case History 1



Existing Structure:

140' - 7'-8"x 5'-5" MULTI-PLATE Pipe-Arch, 10 gage

Reline



- 73"x55", Aluminum, 10 gage, Ultra Flo
- Mannings "n"=0.012
- Service Design Life 100 years plus
- Supplied with 3 stage grout ports, skid rails, leveling rods, internal 10-C bands and flat gaskets, zinc chromate primer exterior.
- Match marked sections

Pulling block



Internal bands w/ flat gasket



Day 2

Bypass piping



Day 3

Flotation bracing



Day 4

Bracing to through 12 o'clock grout port



Vent through Bulkhead



Grout



Grout Port



Day 8 –Last grout lift. Grouting procedure complete.

Grout through vent



Outlet



Lane closure to replace failed roadway slabs. If relines are installed prior to severe deterioration and road failure, all work can be completed with little or no road closure.

Joint Seals



















Flat Bottom Arch Invert Repairs Barry County Road Commission

































CIPP



Cured-in-Place-Pipe

- 30-year plus history of the product
 - Most extensively used trenchless product
- 4" thru 108" diameter
- Gravity/Pressure applications
 - Mainlines and laterals
 - Manholes
- Predominately used within sewers
 - Industrial applications
- Independently verified



CIPP can be utilized for various pipeline concerns:

- Structural
- Environmental
- Strength Enhancement (New construction)
- Infiltration
- Pressure / Gravity Applications
- Lateral Connections
- Point Repairs



CIPP Can Respond quickly!

- Local Installers
- Local Wet out Operations
- In stock materials for standard sizes
- Water / Air Installations
- Most Tube Manufacturing is performed off site in Factory.



**Tube Manufacturing
(ISO Certified)**


Tube Wet Out Process

In-Line Mixer

Gap Rollers

Conveyor

Serial Vacuum



CCTV



Inversion Process


- Water / Air
- Water is most reliable
- Air can offer increased efficiencies




Inversion of Tube


Height

Installation head is typically 4 to 8 psi to produce tight-fitting mechanical locking



Tube Inversion





Once in-place, the process water is heated to cure the thermosetting resins and create a “Cured-in-Place-Pipe”




Curing Process

























URETEK


USA

the soil stabilization and pavement lifting
company that revolutionized the industry

NEXT GENERATION – UDI

URETEK

USA



Requirements for a Successful Project



- **Having appropriate Polymer for Highway work.**
- **Gather Soils Reports, Construction Drawings, and Visit Site to compile information to create a repair plan.**
- **Have Experienced Technicians with Robust DCP unit to test subgrade soils to minus 30 feet, so they can adjust injection plan when on site if necessary.**





Depth ft - in	Number of blows
0' - 4"	asphalt
0' - 8"	pavement
1' - 0"	pavement
1' - 4"	pavement
1' - 8"	21
2' - 0"	18
2' - 4"	15
2' - 8"	5
3' - 0"	3
3' - 4"	4
3' - 8"	3
4' - 0"	2
4' - 4"	1
4' - 8"	2
5' - 0"	1
5' - 4"	0
5' - 8"	2
6' - 0"	1
6' - 4"	3
6' - 8"	4

Depth ft - in	Number of blows
7' - 0"	2
7' - 4"	2
7' - 8"	wor
8' - 0"	wor
8' - 4"	wor
8' - 8"	wor
9' - 0"	wor
9' - 4"	wor
9' - 8"	7
10' - 0"	3
10' - 4"	3
10' - 8"	3
11' - 0"	5
11' - 4"	4
11' - 8"	2
12' - 0"	2
12' - 4"	1
12' - 8"	2
13' - 0"	2
13' - 4"	2

Depth ft - in	Number of blows
13' - 8"	3
14' - 0"	3
14' - 4"	6
14' - 8"	8
15' - 0"	8
15' - 4"	6
15' - 8"	7
16' - 0"	7
16' - 4"	7
16' - 8"	8
17' - 0"	9
17' - 4"	10
17' - 8"	10
18' - 0"	10
18' - 4"	10
18' - 8"	10
19' - 0"	10
19' - 4"	10
19' - 8"	7
20' - 0"	11


POLYURETHANE MATERIAL

- Low viscosity
- 2-component: Resin & Hardener (1:1 by volume)
- Formulated to resist water intrusion into the reaction
- Exothermic chemical reaction generates CO₂ gas
- CO₂ gas causes expansion of the polymer and creates pressure on the surrounding environment

POLYURETHANE MATERIAL

- Rapid Cure –
 - ✓ Reaction complete in < 1 minute
 - ✓ Can support traffic after 20 minutes
 - ✓ Full strength in 24 hours
- Rigid Structural Polyurethane created as the material cures
- Installed density range – 4 to 10 lbs / CF
- Strength varies with density

1 1 TYPICAL INJECTION LAYOUT PLAN VIEW



LEGEND:



URETEK DEEP
INJECTIONS up to -4'.



URETEK DEEP
INJECTIONS up to -8'.



URETEK DEEP
INJECTIONS up to -12'.




Polymer grout bulb - shape
is for illustration only;
shape varies based on soil
conditions, density, etc.

NOTES:

All dimensions, slopes, thickness
of gravels and slabs, etc. are
approximate. DCP testing will be
performed on site to finalize
injection layout.

2 1 TYPICAL INJECTION LAYOUT PROFILE VIEW



Firm Name and Address

URETEK USA
P.O. Box 1929
Tomball, TX 77377

Project Name and Address

**TYPICAL 2 LANE
HIGHWAY - TAPERED
INJECTIONS AROUND
CULVERT**

Project

STANDARD PLAN

Date

7/26/19

Scale

1" = 10'

Sheet

1



Injection inside steel reinforced, plexi-glass box so material flow could be observed



Stabilized soil mass was free-standing
after box removed



Vertical load applied using an excavator



Soil mass would not crush,
but excavator was lifted 11 inches









Bridgman - Culvert

4. Culvert apron 7' X 22' – two injection to 5' depth



Calculation: Deep Injection - apron

100# per injection X \$10.00 X 2 = \$2000.00

Summary:

Bridgman – Culvert Base









